



NEOTHERM

Neoprene Lined Gauntlet

GNL154

Laundering Instructions to maintain hygiene levels

- Hand wash exterior of glove under running water to remove excess dirt, grime etc., using general household soap/cleaner, then wipe them with a dry cloth.
- For machine wash, launder at a maximum temperature of 40°C, maximum speed of 800rpm using standard detergent for 15 to 20 minutes.
- Do not tumble dry.
- Long gentle air drying is recommended
- Partially turn the glove inside out at to the wrist
- Place glove on vertical drying rack
- Dry for several hours in a hot air oven at 50°C maximum

Caution: Hand washing is recommended, machine laundering more than 4 times may alter the glove performance levels.